Work Order Thursday, June 03,			<u>.</u>								Page 1
Item ID: Di Revision ID:	3572-5			Accept					Setup S		
	7/2010 3/2010 4/2010	Start Qty: 12.00 Req'd Qty: 12.00	: ! ##		Cust Item I Customer:	D:				1100011	
		n:	Date:			ite:		F		tart	
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Numbe	Insp. er Stamp
Draw Nbr	Revi	sion Nbr									
D3572	Rev I	D					/		N-d		
Waterjet FLOW CNC Waterjet		FLOW WATER JET Memo 1-Cut as per Deburr if ner		0.00 0.00 Д □Prog Rev: -	▶ □2-			R	0-6-	8	
110 . QC Quality Control		QC2- Inspect parts off m Memo	achine FAI/FAIB	0.00				<u>12</u> 10	<u>-6-8</u>		
120 QC		QC8- Inspect parts - seco	nd check	0.00	ماره اس		((42c)		

Quality Control

Dart	Aero	space	Ltd
------	------	-------	-----

	•								* _
W/O:			V	ORK ORDER CHAI	NGES				
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Da	ate Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
					:				:
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Ye	s No	DQA:	Date: _	
		esolution:							
NCR:			WORK OR	DER NON-CONFOR	MANCE (NO	CR)			
DATE	STEP	Description of NC			Section B	\	/erification	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	on Sign Da	n &	Section C	Chief Eng	QC Inspector
		•							
			•	•					

Page 2

Item ID:

D3572-5

Accept



Setup Start



Revision ID:

Item Name: **Start Date:**

Bracket

6/3/2010

Start Qty: 12.00 Reg'd Oty: 12.00

Cust Item ID:

Customer:

Reference:

Required Date: 6/4/2010

Approvals:

Process Plan:

Date: Tooling:

Date:

Date:

Run

Start Stop

Stop

Sequence ID/

Work Center ID

Date: _____

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Tool # Plan

Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

130

Brake NC

Brake NC

Operation Description

NC BRAKE

Memo

Memo

0.00

0.00

5610106/16

20

140

OC

Quality Control

QC5- Inspect part completeness to step on W/O

Identify as per dwg & Stock Location: 7

0.00

Packaging

Memo

0.00

10.6-17 (2003)

Packaging

form bend as per Dwg D3572 usin DT8943

150

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			V	ORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	<u> </u>									
Part No		PAR #:								
	R	esolution:	Dispositi	on:	QA:	N/C Cld	sed:		Date:	· · · · · · · · · · · · · · · · · · ·
NCR:		V	VORK ORI	DER NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC	Initial		ion B	Cian 9	Verifica		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		Sign & Date	Section	С	Chief Eng	QC Inspector
		·								
	1	1	1 1		i					•

Wո	rk	Ω	der	ID	594	105
* * U	I IN	VI	ucı	w	・・ファー	IUJ

Thursday, June 03, 2010 1:34:01 PM



Page 3

Item ID:

D3572-5

Accept



Setup Start

Stop



Revision ID:

Item Name: **Start Date:**

Bracket

6/3/2010

Start Qty: 12.00

Req'd Qty: 12.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



Required Date: 6/4/2010

QC:

Date: SPC (Y/N):

Date:_

Stop



Sequence ID/

Operation **Work Center ID** Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours** **Tool ID**

Tool # Plan

Accept Code Qty

Reject Qty

Reject Number

Insp. Stamp

160

QC

Quality Control

Memo

0.00

0.00

Dart Aeros	pace Ltd
------------	----------

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		711								
Part No	:	PAR #:	Fault Cate	egory:	NCE	r Yes 1	No DO	Δ-	Date:	
		olution:								
NCR:				ER NON-CONFORMA						
DATE	STEP	Description of NC			ion B		Verific	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
						-				
				•						

Picklist Print

Thursday, June 03, 2010 1:34:00 PM

Work Order ID: 59405

33403

D3572-5

Parent Item Name:

Parent Item:

Bracket

Comments: IPP

IPP Rev : A New Issue 07-01-16 JLM



Start Date: 6/3/2010

Required Date: 6/4/2010

Page 1

Start Qty: 12.00

Required Qty: 12.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6S.080		Purchased	No	-			sf	157.4419	0.03	0.360180		6	
											12-11-6	_	

6061-T6 .080 Sheet

114351



Dart Aerospace	Ltd
----------------	-----

W/O:			W	ORK ORDER CHANG	iES				***	
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										•
Part No	:	PAR #:	Fault Cat	egory:	_ NCI	R: Yes I	do DQ	4:	Date:	
		esolution:								
NCR:		V	WORK ORI	DER NON-CONFORMA	ANCE	(NCR				
DATE	STEP	Description of NC			ion B		Verific	eation	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C	Chief Eng	QC Inspector	
				:						ı
						·				
						·				
					·					
	:									

DART AEROSPACE LTD	Work Order:	5 9405
Description: Bracket	Part Number:	D3572-5
Inspection Dwg: D3572 Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype
-----------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
1.00	+/-0.030	1,004	7					
5.25	+/-0.030	5,850	٠.					
0.080	+/-0.010	6801	>					
		-						
A-9-4								
					·			
			<u> </u>					


Measured by:	B	Audited by:	5	Prototype Approval:	N/A
Date:	10-6-8	Date:	10/66/08	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.05.01	New Issue	KJ/JLM	
В	09.12.14	Dwg Rev updated	KJ 🛠	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES							, .	· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PROCEDURE CHANGE				у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		:							<u> </u>	
					,					
				d.				-		
							٠			
Part No	•	PAR #:	Fault Cate	gory:	NCR: Y	es N	lo DQ /	A :	Date:	
Resolution:			Dispositio	Disposition: QA			QA: N/C Closed: Date			
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	ICR)				•
DATE	STEP	Description of NC	In this I	Corrective Action Section B			Verific			Approval QC Inspector
		Section A	Initial Action Descrip Chief Eng Chief Eng		ion Sign & Date		Section C			
		a de la companya de l								

[→] H:\fFOP\MS\Quality Assurance\approved QA\NCRWO RevE



Dart	Aer	ospa	ıce	Ltd
------	-----	------	-----	-----

W/O:		WORK ORDER CHANG							
DATE STEP		PROCEDURE CHANGE					Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1 100 11191	
				_					
									1
Part No	•	PAR #:	Fault Ca	tegory:	NC	R: Yes	No DQA: _	Date: _	
Resolution:			Disposit	ion:	QA	: N/C CI	Date: _	Date:	
NCR:			WORK ORI	DER NON-CONFO	PRMANCI	E (NCR	R)		
DATE	STEP	Description of NC			Section B		Verification	n Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Descrip	otion	Sign & Date	Section C	Chief Eng	QC Inspector
					,				
						1			
					<u> </u>				